

# BOROUGH OF TARENTUM

REDCAT ELECTRIC DEPARTMENT 318 E. SECOND AVENUE TARENTUM, PENNSYLVANIA 15084 724.224.181

## **Bi-Monthly Report**

August 2025

Emergency Outages: 288 Planned Outages: 4 Overtime Hours: 11

## **System Operations**

- Outages reported and cause (if known)
  - WPP substation issue dropped the South Tarentum circuit
  - 1 house meter issue
  - Two 1 house outage issues
- Restoration times and response summary
  - Response was immediate for WPP
- System inspections completed (poles, transformers, lines)
  - SP project prep
- Smart meter data/alerts reviewed
  - Attempt to review alerts daily

#### **Maintenance & Repairs**

- Preventive maintenance completed
  - Troubleshot 221 James Wolf BLVD Transformer bank
  - o 2 houses disconnect/reconnect
  - o Demoed 1 pole for pole pulling
  - Troubleshoot Transformer bank @ 2000 degrees F
  - 1 house disconnect/reconnect
  - Installed new triplex
  - Built image package for tree trimming
- Transformers or fuses replaced
  - o 0 fuses
- Bucket truck use or repairs
  - o N/A
- Line clearance or tree trimming work
  - Tree trimming, golden towers and Electric
  - Tree trimming, Water tower feed

## **Projects & Capital Improvements**

- New services connected or meters replaced
  - 0
- Budget or procurement needs
  - Need new big bucket truck (I talked to Altec, they are unaware of any 3<sup>rd</sup> party to conduct proper boom electrical inspections.)

#### **Regulatory & Safety**

- Incident reports or near-misses
  - N/A
- PPE inventory or equipment needs
  - Roughly shoulder high thin rubber gloves for working in transformer oil (possibly containing PCBs)
  - Above the Elbow" thin rubber gloves to safely work inside transformers, preventing skin to oil contact.

## **Other Items**

- Community complaints addressed
  - o N/A
- Coordination with other departments or utilities
  - o WPP communication through outage
- Future planning or concerns
  - More to follow
- Other work or items:
- MORE TO FOLLOW