

## Tarentum Water Plant October 2020 Boro Report

Water Processed.....29.4mg

Overtime hrs.....40hrs

Maintenance performed not including daily routine testing, sampling,  
and maintenance

Dredging samples taken to be analyzed

Replaced lights in basin area to reduce energy consumption

Changed oil in plant vehicle

Filter room computer upgraded for Windows 10 and SCADA System  
reinstalled